





Schema 2



To avoid voltage loss, connect the 12V main output cables from the power supply to each other.



When placing power supply units, there must be at least 15 cm between the power supply units.